

MATERIAL SAFETY DATA SHEET

Product:	BD-6	<i>Note: The information herein is given in good faith. No warranty, expressed or implied, is made.</i>	
Printed:			
Printed For:			
Original Issue Date:	11/12/85	Approved By:	Chuck Hiddema
Revision No. 6 Date:	07/26/01		V.P. Technical Operations
Section I - Identification			
Manufacturer:	AGS Company		
Street Address:	2651 Hoyt St		
City/State/Zip	Muskegon Hts., MI 49444		
Phone:	800-253-0403		
Phone:	231-733-2101		
FAX:	231-733-1784		
Transportation Emergency:	CHEM-TEL		
Phone:	800-255-3924		
Trade Name:	Belt-Ease Belt Dressing Aerosol		
Catalog No.:	BD-6		
Common Name:	BELT-EASE		
Container/Size:	Aerosol, 4 oz.		
NFPA - Health:	1		
Flammability:	2		
Reactivity:	0		
Specific Hazard:			
HMIS - Health:	1		
Flammability:	2		
Reactivity:	0		
Protective Equipment:	A		
Section II - Hazardous Ingredients			
Hazardous Ingredient	CAS No.	Wgt. %	TLV
1 Aliphatic Petroleum Naphtha	8052-41-3	75-85	100 ppm (500 ppm PEL)
2 Polybutene Polymer	9003-29-6	15-25	Not Assigned
3 Carbon Dioxide	124-38-9	1-5	5000 ppm
4			
5			
6			
7			
8			
9			
10			
NOTES:			

Section III Physical Data			Catalog No. BD-6
pH - Supplied:	Not Determined		
pH - Diluted:	Not Determined		
Water Solubility:	Nil		
Specific Gravity:	(Water=1) 0.82		
Melting Point:	Not Applicable		
Boiling Point:	Not Determined		
% Volatiles:	67%		
Vapor Pressure:	Not Determined		
Vapor Density:	(Air=1) > 1		
Evaporation Rate:	Not Determined		
Appearance:	Clear liquid with petroleum odor in an aerosol package.		
Section IV Fire & Explosion Data			
Flash Point:	> 100° F(liquid)		
Method:	T.C.C.		
Auto Ignition Temperature:	Not Determined		
Flammable Limits In Air	LEL: Not Determined		
	UEL: Not Determined		
Extinguishing Media:	Carbon dioxide, dry chemical, foam and/or water fog.		
Special Procedures:	Wear self-contained breathing apparatus. Water fog may be used to reduce vapor concentration.		
Unusual Hazards:	Vapors are heavier than air and accumulate in low areas.		
Section V - Reactivity Data			
Unstable and/or Auto Reactive:	Stable		
Incompatible Materials:	Oxidizers		
Hazardous Decomposition Products:	Oxides of carbon.		
Section VI - Emergency First Aid			
Eyes:	Flush with water for at least 15 minutes. Get medical attention.		
Skin:	Wash with soap and water. Remove contaminated clothing. If adverse effects occur, consult a physician.		
Ingestion:	Keep patient quiet. Do not induce vomiting. Get medical attention.		
Inhalation:	Remove to fresh air. Administer oxygen or artificial respiration as needed. Get medical attention.		
Section VII - Health Effects			
Eyes:	May cause discomfort and irritation.		
Skin:	May cause irritation, defatting, dermatitis. Contaminated clothing may cause severe irritation.		
Ingestion:	May cause nausea, vomiting and irritation of G. I. Tract.		
Inhalation:	Acts as a CNS depressant and may cause irritation of upper respiratory system.		
Other Effects:	Aspiration into lungs may cause chemical pneumonitis.		

Section VIII - Ventilation and Protective Measures		Cat. No. BD-6	
Ventilation Requirement:	Suitable to maintain concentrations below TLV.		
Eyes:	Yes		
Gloves:	Yes		
Clothing:	No		
Respiratory:	Yes		
Other:	Eye bath and safety shower in work area.		
Section IX - Storage and Handling Procedures			
Conditions to Avoid:	Excessive and/or direct heat, do not puncture or incinerate.		
Section X - Spill Procedures and Waste Disposal			
Spill Procedure:	Remove ignition source. Absorb on an inert material and place in appropriate container for disposal.		
Disposal Method:	Removal by an approved, licensed waste hauler.		
EPA Waste I.D. NO.:	D001		